Romford Rail Operating Centre New Training Area Construction



Best Practice Case Study



Project Data

Client : Network Rail Location : Romford Essex Main Contractor : Taziker Completed : 2021

Project Overview

The works are located within Network Rail's Romford Rail Operating Centre (ROC) which incorporates Data Centres, Signal Operations, Crossrail Operations, training and IT services within a 3 storey building.

Due to ongoing increase in training requirements additional facilities were required and an area was identified on the second floor within the existing building for the expansion/ alteration.

Scope Of Work

NCCT were contracted to carry out the installation of a new training area on the second floor.

The works included the installation of partial height acoustic screens to the training area, a new Comms Room with full height partitions and associated mechanical and electrical works.

The building and client operations were fully functional 24 hours a day ,every day of the year and NCCT worked adjacent to these occupied areas , co-ordinating and managing the works accordingly to minimise the disruption to the occupants at all times .



NCCT Ltd ,Unit 7, Optima Park, Dartford, Kent, DA1 4QX. Tel :+44(0)1322 558 806 E Mail:info@ncct.co.uk www.ncct.co.uk